

FIG.1




FIG.2

006T50:006H2560




FIG.3




FIG.4




FIG.5




FIG.6

b^2	0	b^2	0	b^2
0	$2ab$	$2ab$	$2ab$	0
b^2	$2ab$	$4a^2 + 8b^2$	$2ab$	b^2
0	$2ab$	$2ab$	$2ab$	0
b^2	0	b^2	0	b^2

FIG.7




FIG.8